




项目负责人

数量

借(通)用件登记

描图

描校

旧底图总号

底图总号

签字

日期

|    |    |    |       |    |     |           |     |    |
|----|----|----|-------|----|-----|-----------|-----|----|
|    |    |    |       |    |     | CYC 正阳实业  |     |    |
|    |    |    |       |    |     | 爆炸图(230V) |     |    |
| 标记 | 处数 | 分区 | 更改文件号 | 签名 | 年月日 | 阶段标记      | 重量  | 比例 |
| 设计 |    |    | 标准化   |    |     |           |     |    |
| 校对 |    |    |       |    |     |           |     |    |
| 审核 |    |    |       |    |     |           |     |    |
| 工艺 |    |    | 批准    |    |     | 共 张       | 第 张 |    |

J1X17-210-001A

## J1X-KZ17-210爆炸图英文清单(230V)

共 2 页 第 1 页

| 序号 | 名称及规格                       | 数量 | 序号 | 名称及规格                        | 数量 |
|----|-----------------------------|----|----|------------------------------|----|
| 1  | cross panhead screw M5X20   | 2  | 40 | cross panhead screw ST4.2x70 | 2  |
| 2  | big washer                  | 1  | 41 | stator                       | 1  |
| 3  | active cover                | 1  | 42 | cross panhead screw ST4.8x60 | 2  |
| 4  | six hole caul               | 1  | 43 | handle                       | 1  |
| 5  | tower spring                | 1  | 44 | cross panhead screw ST4.2x18 | 7  |
| 6  | dock panel locking screw    | 1  | 45 | top handle                   | 1  |
| 7  | active cover dock panel     | 1  | 46 | seich button                 | 1  |
| 8  | cross panhead screw M6X8    | 1  | 47 | switch                       | 1  |
| 9  | rivet                       | 3  | 48 | capacitor                    | 1  |
| 10 | active cover board          | 1  | 49 | cross panhead screw ST4.2x13 | 2  |
| 11 | top link                    | 1  | 50 | cable pressboard             | 1  |
| 12 | hex locking nut M5          | 2  | 51 | below handle                 | 1  |
| 13 | middle link                 | 1  | 52 | brush holder end cap         | 2  |
| 14 | below link                  | 1  | 53 | carbon brush                 | 2  |
| 15 | link screw                  | 2  | 54 | brush holder                 | 2  |
| 16 | Screw M8x16-L               | 1  | 55 | cross panhead screw M5X45    | 4  |
| 17 | saw balde side board        | 1  | 56 | housing                      | 1  |
| 18 | saw $\phi$ 210              | 1  | 57 | Shaft                        | 1  |
| 19 | saw balde inner board       | 1  | 58 | rocking arm shaft            | 1  |
| 20 | cross flat head screw M4X10 | 5  | 59 | rocking arm                  | 1  |
| 21 | active clamp                | 1  | 60 | inner hex screw M6x30        | 4  |
| 22 | tailshaft                   | 1  | 61 | hex nut M6                   | 5  |
| 23 | bearing 6002-2Z             | 1  | 62 | rocking arm pointer          | 1  |
| 24 | cross panhead screw M5X16   | 2  | 63 | cross panhead screw M4X10    | 8  |
| 25 | spring washer 5             | 8  | 64 | washer 4                     | 8  |
| 26 | washer 5                    | 9  | 65 | stop flat                    | 1  |
| 27 | control button spring       | 1  | 66 | big washer 8                 | 1  |
| 28 | control bar                 | 1  | 67 | rocking arm locking handle   | 1  |
| 29 | control base                | 1  | 68 | washer 12                    | 1  |
| 30 | gear box cover              | 1  | 69 | hex locking nut M12          | 1  |
| 31 | big gear                    | 1  | 70 | open circlip 6               | 1  |
| 32 | saw cover twisting spring   | 1  | 71 | saw cover locking arbor      | 1  |
| 33 | saw cover                   | 1  | 72 | O-ring $\phi$ 4.5x1.8        | 1  |
| 34 | bearing 6200-2Z             | 1  | 73 | inner hex screw M6x16        | 1  |
| 35 | self-lock bar spring        | 1  | 74 | rocking arm base             | 1  |
| 36 | self-lock bar               | 1  | 75 | inner hex screw M6x12        | 4  |
| 37 | self-lock bar stoping screw | 1  | 76 | locking screw                | 1  |
| 38 | wind guide                  | 1  | 77 | fence                        | 1  |
| 39 | rotor                       | 1  | 78 | backing board                | 1  |

编制:

校对:

审核:

批准:

## J1X-KZ17-210爆炸图英文清单(230V)

共 2 页 第 2 页

| 序号  | 名称及规格                                             | 数量 | 序号 | 名称及规格 | 数量 |
|-----|---------------------------------------------------|----|----|-------|----|
| 79  | hex bolt M6X25                                    | 1  |    |       |    |
| 80  | turntable                                         | 1  |    |       |    |
| 81  | array nut M6                                      | 4  |    |       |    |
| 82  | cross flat head screw M4X6                        | 1  |    |       |    |
| 83  | protecting plate                                  | 1  |    |       |    |
| 84  | base                                              | 1  |    |       |    |
| 85  | protect cover                                     | 1  |    |       |    |
| 86  | big washer 6                                      | 1  |    |       |    |
| 87  | hex locking nut M6                                | 1  |    |       |    |
| 88  | ball $\phi 8$                                     | 1  |    |       |    |
| 89  | ball spring                                       | 1  |    |       |    |
| 90  | inner hex locating screwM10x10                    | 1  |    |       |    |
| 91  | axle spring collar 12                             | 1  |    |       |    |
| 92  | oil bearing ( $\phi 8 \times \phi 12 \times 10$ ) | 1  |    |       |    |
| 93  | bearing 608-2Z                                    | 1  |    |       |    |
| 94  | 608 bearing jacket                                | 1  |    |       |    |
| 95  | parallel key 4×5×13                               | 1  |    |       |    |
| 96  | protect block                                     | 1  |    |       |    |
| 97  | cross panhead screw M5X12                         | 2  |    |       |    |
| 98  | cable jacket                                      | 1  |    |       |    |
| 99  | cable                                             | 1  |    |       |    |
| 100 | wire hander                                       | 1  |    |       |    |
| 101 | dust catcher bag                                  | 1  |    |       |    |
| 102 | 6mm inner hex spanner                             | 1  |    |       |    |
| 103 | 5mm inner hex spanner                             | 1  |    |       |    |
| 104 |                                                   |    |    |       |    |
| 105 | screw M6X16                                       | 3  |    |       |    |
| 106 | press pole                                        | 1  |    |       |    |
| 107 | press screw pole                                  | 1  |    |       |    |
| 108 | press plank                                       | 1  |    |       |    |
| 109 | press board                                       | 1  |    |       |    |
| 110 | axle spring collar 5                              | 1  |    |       |    |
| 111 | backing angel pointer                             | 1  |    |       |    |
| 112 | screw M6X22                                       | 2  |    |       |    |
| 113 | Bracket                                           | 2  |    |       |    |
| 114 | Sliding fence                                     | 1  |    |       |    |
| 115 | Cover                                             | 1  |    |       |    |
|     |                                                   |    |    |       |    |
|     |                                                   |    |    |       |    |

编制:

校对:

审核:

批准: